

# RENAULT CAPTUR Captur E-Tech full hybrid 145 esprit Alpine



VIN NO VF1RJB00174892244 Registration Number HD821JD

<b>=</b> -	<b>•</b>	<b>2</b> 025-05-02	<b>=</b> -
Last Service	Last Service Mileage	First Registration Date	Country First Registered
<b>☆</b> -	<b>: •</b> -	<b>P</b> 1	999999 km
MOT Date	Number of Owners	Number of Keys	Odometer Reading

## **Inspection Report Summary**


Customer	BCAuto Encheres	Report Number	P20251007161709
Inspection Date / Place	2025-10-07 / BCA COIGNIERES	Cosmetic Grade	4

## Vehicle Summary

Vehicle Condition	Not Movable	VAT Type	Qualified - Normal Rate
Fuel Type	Plug - in Hybrid Electric Vehicle Petrol	Gearbox Type	Automatic
Colour	Blue	Engine Size (cc)	1598
Engine Size	1.6	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Charging Cables		WLTP CO2 Emissions	
Accident Damage	Yes	Euro Emission	

## Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	
Manufacturer Warrenty			








# **Equipment Details**

Seat Heating	No	Air Conditioning	Yes
Sunroof Type	Tilt/Slide Steel		

# Cosmetic Damage



	Component	Damage	Comments
1	Corner Bumper / Front Right	Missing Part	
2	Corner Bumper / Front Left	Missing Part	
3	Seat / Back Left	Interior / Missing	
4	Dashboard / Front	Interior / Missing	
5	Fender / Back Right	Paint / Scratch / Line	
6	Dashboard / Front	Interior / Missing	
7	Fender / Back Right	Paint / Scratch / Line	



1. Corner Bumper / Front Right Missing Part -

2. Corner Bumper / Front Left Missing Part -



3. Seat / Back Left Interior / Missing -

4. Dashboard / Front Interior / Missing -



5. Fender / Back Right Paint / Scratch / Line -

6. Dashboard / Front Interior / Missing -



7. Fender / Back Right Paint / Scratch / Line -

#### **Mechanical Condition**

#### Tyres

Presence Anti-Theft Lock Nut



- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- NA Not applicable
- Not tested

#### **Disclaimer Section**

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.