

INSPECTION REPORT


End of contract

GENERAL INFO

File	294553
License plate	2CBL136
Vehicle identification number	VF1RJB00469148851
Dossier	2021 343 156
Make	Renault Captur TCe 90 Corporat
Mileage	90576
First registration	20/05/2022
client availability date	19/09/2025
inspectionDate	23/09/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
15	Bumper Front // Replace & Painting	N
237	Wing Front right / Trim / Replace	N
272	Bumper Front / Trim Right / Replace	N
275	Bumper Front / Grid Right / Replace	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
282	Bumper Rear / Trim Center / Replace	N
194	Door Rear Right // Repair & Painting	N
197	Door Rear Right / Trim / Replace	N
214	Door Front Right // Repair & Painting	N
217	Door Front Right / Trim / Replace	N
159	Rear Bonnet / Rear Window / Replace	Y
165	Roof // Polish	Y
203	Rocker Panel Right // Repair & Painting	Y
311	Wheel Alloy Front Left // Repair	N
324	Wheel Rear Left / Wheel Cover / Replace	Y
534	Trunk Compartment / Carpet / Replace	Y


Damage Pictures



Damage within Renta-norm-scratch




Wheel Rear Left / Wheel Cover / Replace-scratch



Rocker Panel Right // Repair & Painting-scratch + dent



Trunk Compartment / Carpet / Replace-missing



Roof // Polish-Chemical reaction




Wheel Alloy Front Left // Repair-scratch



Rear Bonnet / Rear Window / Replace-scratch



Bumper Front / Grid Right / Replace-tear



Bumper Front // Replace & Painting-tear



Wing Front right / Trim / Replace-N comf / out of order




Bumper Front / Trim Right / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-dent



Bumper Rear / Trim Center / Replace-scratch




Door Rear Right // Repair & Painting-scratch + dent



Door Front Right // Repair & Painting-scratch + dent



Door Front Right / Trim / Replace-scratch



Door Rear Right / Trim / Replace-scratch