



**Renault Captur: S463ZL**

Vinnumber:	<b>VF1RJB00671053384</b>	Versionname:	<b>Captur 1.0 TCe 67kW Evolution</b>
First Registrationdate:	<b>9/05/2023</b>	Fiscalpower:	
Expertise Mileage:	<b>71502</b>	Power Kw:	<b>67</b>
Bodytype:		Body colour:	<b>Gris Highland</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>Front</b>	Type of rims (mounted):	<b>Steel</b>
Fueltype:	<b>Petrol</b>	Parking lot:	<b>715</b>
Number of seats:	<b>5</b>		
Type of rims (mounted):	<b>Steel</b>		
Maintenance needed:	<b>No</b>		

**Options**

Number of keys total	<b>1</b>	Telephone equipment
GPS		Central consol F
Manual climate control		Luggage cover
Windows electric F		Headlights Xenon/LED/Laser
Radio multimedia		Rear parking sensors

**Tyres**

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 60 / 17 / 96 / H / Steel	5,5 mm	Goodyear	All season
	Right	215 / 60 / 17 / 96 / H / Steel	5,1 mm	Goodyear	All season
Rear	Left	215 / 60 / 17 / 96 / H / Steel	6,8 mm	Goodyear	All season
	Right	215 / 60 / 17 / 96 / H / Steel	6,4 mm	Goodyear	All season

**Assistance equipment**

Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>0</b>

**Ignition key, Missing, Replace**

*No pictures to display*

**Wheel arch cover RL, Scratch(es), Replace**



**Bonnet, Dent(s), Repair and paint (complete)**



**Door RR, Dent(s) and scratch(es), Repair and paint (complete)**



**Outside rear-view mirror housing R, Scratch(es), Replace and paint**



Wheel arch cover FR, Scratch(es), Replace



Bumper corner RL, Scratch(es), Repair and paint (complete)



Bumper corner RR, Scratch(es), Repair and paint (complete)



Roof, Stone chip(s), Repair and paint (complete)

