

Vehicle details

VIN	VF1RJB007 66002574	Brand	RENAULT	Maintenance date	-
Licence Plate	J0-91-PK	Model	Captur TCe 100 Intens 5d	Maintenance mileage	-
Registration date	25/09/2020	Year	2020	Exterior Color	Blue Solid
Odometer	86 243 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	24/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Alloy wheel rims	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Spare key	✓
Remote key	✓

Tyres

Hankook 215/60/17 Summer 7.0 mm



Hankook 215/60/17 Summer 7.0 mm



Pirelli 215/60/17 Summer 4.0 mm

Pirelli 215/60/17 Summer 4.0 mm

Exterior

1



●●

Part	Door
Position	Back left
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

2



●●

Part	Step plate
Position	Back left
Damages	Dent & Chips
Severity	-
Repair mode	For info

3



●●

Part	Door
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

4



●●

Part	Door
Position	Front right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

5



●●●

Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

6



●●●

Part	Unpainted bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

7



●●

Part	Registration plates
Position	Front
Damages	Not conform
Severity	-
Repair mode	For info

8



●●

Part	Bonnet
Position	-
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

9



●●●●●●●●

Part	Roof
Position	-
Damages	Hail damaged
Severity	Diameter (mm) > 20
Repair mode	Smart Repair