



RENAULT KANGOO VU

KANGOO EXPRESS BLUE DCI 80 EXTRA R-LINK

VIN NO VF1WF000167237765
Registration Number FZ029QX



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

Customer	BCA Auto Encheres	Report Number	P20250613091110
Inspection Date / Place	2025-06-13 / BCA ANGOULEME	Cosmetic Grade	3


Vehicle Summary

Vehicle Condition	Not Movable	VAT Type	Qualified - Normal Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour	White	Engine Size (cc)	1461
Engine Size	1.5	No of Doors	5
Body Type	Box Wagon	Drive Train	Front
Seat Colour		No of Seats	2
Charging Cables		WLTP CO2 Emissions	

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	
Manufacturer Warranty			





Equipment


Central locking	Radio	Cruise control	Electrically folding wing mirrors
Rear parking sensors	Satellite navigation		

Equipment Details


Seat Heating	No	Air Conditioning	Yes
--------------	----	------------------	-----

Cosmetic Damage

5 Dommages



3 Dommages



Component		Damage	Comments
1	Floor Carpet	Interior / Dirty	
2	Seat / Front Left	Interior / Dirty	
3	Floor Carpet	Interior / Dirty	
4	Windshield / Front	Glass Break	
5	Mirror Shell / Front Left	Bodywork / Breakage	
6	Mirror / Front Left	Bodywork / Breakage	
7	Side Panel	Paint / Scratch / Line	
8	Mirror / Front Right	Bodywork / Breakage	



1. Floor Carpet
Interior / Dirty -



2. Seat / Front Left
Interior / Dirty -




3. Floor Carpet
Interior / Dirty -



4. Windshield / Front
Glass Break -



5. Mirror Shell / Front Left
Bodywork / Breakage -



6. Mirror / Front Left
Bodywork / Breakage -



7. Side Panel
Paint / Scratch / Line -



8. Mirror / Front Right
Bodywork / Breakage -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut ✓

✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage

! Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

⊠ Not tested

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.