



PEUGEOT 3008

3008 1.2 Puretech 130ch S&S BVM6 Allure

VIN NO VF30UHNMF5122961
Registration Number DR025LW



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	-	2	62623 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2015-05-13	-

Inspection Report Summary

Customer	BCA Auto Encheres	Report Number	P20251009110325
Inspection Date / Place	2025-10-09 / BCA MONTMARTIN	Cosmetic Grade	2

Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Exempt Rate
Fuel Type	Petrol	Gearbox Type	Manual
Colour	White	Engine Size (cc)	1199
Engine Size	1.2	No of Doors	5
Body Type	Hatchback	Drive Train	Front
Seat Colour		No of Seats	5
Charging Cables		NEDC CO2 Rating (q/km)	115
Engine Rating CV	7	Metalic Colour	No
Accident Damage	No	Euro Emission	

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment


Central locking	Radio	Alloys wheels	Tow ball
Front fog lamps	Power assisted steering	Electrically folding wing mirrors	Rear parking sensors
Stability control	Cruise control	Front parking sensors	Satellite navigation

Equipment Details


Seat Heating	No	Air Conditioning	Yes
Sunroof Type	Fixed Panoramic		

Cosmetic Damage

5 Dommages



1 Dommages



Component		Damage	Comments
1	Floor Carpet	Interior / Dirty	
2	Rim / Front Right	Out of Bodywork / Scratch	
3	Rim / Back Left	Out of Bodywork / Scratch	
4	Rim / Front Left	Out of Bodywork / Scratch	
5	Rim / Back Right	Out of Bodywork / Scratch	
6	Door / Front Right	Paint / Scratch / Scuff	




1. Floor Carpet
Interior / Dirty -



2. Rim / Front Right
Out of Bodywork / Scratch -




3. Rim / Back Left
Out of Bodywork / Scratch -



4. Rim / Front Left
Out of Bodywork / Scratch -



5. Rim / Back Right
Out of Bodywork / Scratch -



6. Door / Front Right
Paint / Scratch / Scuff -

Mechanical Condition


Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.