

Inspection Protocol

PEUGEOT PARTNER VAN UTÖKAD LAST 1.6 BLUEHDI

Vehicle information

License plate	MRA579	Inspected by	
Year model	2018	Date of inspection	2025-04-11
Manuf. year/month	2018-02	City	-
First day in traffic	2018-02	Keys	-
Colour	Ljusgrå	Service book	
Mileage	108 300 km	Latest service	-
Fuel	Diesel	Mileage at the latest service	-
Transmission	Manuell	Summer tires	No data
Engine effect	73 kW	Winter tires	No data

Damages

Location	Damage	Comments	Costs excluding VAT
Front	Repa	repa vänster fram	-
Front	Spricka	spricka i glaset, nedre delen	-

Total excl. VAT	0 €
-----------------	-----

Images

[See all images in large format](#)

















