



Peugeot Partner (Segm. B1): 1UGK355

Vinnumber:	VF37FBHY6JJ580636	Versionname:	Partner Premium 121 L2H1 1.6 BlueHDi S/S
First Registrationdate:	3/05/2018	Fiscalpower:	100pk/cv 5p
Expertise Mileage:	140993	Power Kw:	73
Bodytype:		Type of rims (mounted)	Steel
Gearbox:	MAN 5 VIT		
Transmission:			
Fueltype:			
Battery functioning	Yes		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Light Commercial Vehicle		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Type of Tow bar	No Tow bar
Type of Maintenance book	Maintenancebook missing		
Type of GPS storage	N.A.		

Tyres

195/65/15/91 T				
Summer tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 6 mm
Tyre profile depth FL				7.0
Tyre profile depth FR				6.0
Tyre profile depth RL				7.0
Tyre profile depth RR				6.0
Tyre size FL				195/65 R 15 91 T
Tyre size FR				195/65 R 15 91 T
Tyre size RL				195/65 R 15 91 T
Tyre size RR				195/65 R 15 91 T
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Dashboard, Hole, Smart repair



Centre console, Hole, Smart repair



Instrument panel, complete, Not functioning (well), Check



Interior, Not original part, Check



Engine insulation, Missing, Check



Grille, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Replace



Door FL, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable



Wing trim RL, Scratch(es), Replace



Boot door panel RL, Scratch(es), Spot repair



Bumper R, Scratch(es), Replace



Boot door panel RL, Dent(s) and scratch(es), Repair and paint (complete)



Boot door panel RR, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Bad repair, Replace



Outside rear-view mirror base R, Bad repair, Replace



Roof pillar R, Dent(s) and scratch(es), Repair and paint (complete)



Sliding door R, Scratch(es), Acceptable



Bodywork, Not original part, Remove lettering



Roof, Dent(s), Repair and paint (complete)



Bodywork, Not original part, Check

