



PEUGEOT 508 Berlina Diesel  
508 1.6 bluehdi Feline s&s 120cv auto

VIN NO VF38DBHZZTGL007858  
Registration Number FG675AA



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2024-12-13	-	-	207063 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2016-12-05	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20251002113637
Inspection Date / Place	2025-10-02 / BCA Lodi	Cosmetic Grade	5

Vehicle Summary



Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Automatic
Colour	White	Engine Size (cc)	1560
Engine Size	1.6	No of Doors	4
Body Type	Sedan	Drive Train	Front
Seat Colour	Black	No of Seats	5
Seat Covering Name		Seat Covering	Leather
Charging Cables		NEDC CO2 Rating (q/km)	102

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			









Equipment

Central locking	Rear parking sensors	Digital Radio	Satellite navigation
Remote adjusting wing mirrors	Cruise control	Tyre Mobility Kit	Power assisted steering
Alloys wheels	Electrically adjustable seats	Volante multifuncion	Remote central locking
Trip Computer	Stability control		


Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Summer	
	KLEBER KLEBER-DYNAXER UHP	235/45//R18 - 98Y / 4 mm
	KLEBER KLEBER-DYNAXER UHP	235/45//R18 - 98Y / 4 mm
	KLEBER KLEBER-DYNAXER UHP	235/45//R18 - 98Y / 4 mm
	KLEBER KLEBER-DYNAXER UHP	235/45//R18 - 98Y / 4 mm

Cosmetic Damage

20 Danni



2 Danni



Component		Damage	Comments
1	Panel Filling / Front Left	Interior / Broken	
2	Steering Wheel / Front	Interior / Worn - out	
3	Windshield / Front	Glass Break / Impact	
4	Hood	Paint / Chipping	
5	Bumper / Front	Bodywork / Dent	
6	Bumper / Front	Bodywork / Dent	
7	Rim / Front Left	Out of Bodywork / Scratch	
8	Fender / Front Left	Bodywork / Dent	
9	Door / Front Left	Paint / Scratch / Line	
10	Door / Back Left	Paint / Scratch / Line	
11	Rim / Back Left	Out of Bodywork / Scratch	
12	Fender / Back Left	Bodywork / Dent	

13	Bumper / Back	Bodywork / Dent
14	Tailgate	Bodywork / Dent
15	Fender / Back Right	Bodywork / Dent
16	Rim / Back Right	Out of Bodywork / Scratch
17	Rocker Panel / Center Right	Bodywork / Dent
18	Door / Front Right	Bodywork / Dent
19	Mirror Shell / Front Right	Paint / Scratch / Line
20	Fender / Front Right	Bodywork / Dent
21	Rim / Front Right	Out of Bodywork / Scratch
22	Roof	Bodywork / Dent / Hail Area






1. Panel Filling / Front Left Interior / Broken -



2. Steering Wheel / Front Interior / Worn - out -



3. Windshield / Front Glass Break / Impact -



4. Hood Paint / Chipping -



5. Bumper / Front Bodywork / Dent -



6. Bumper / Front Bodywork / Dent -







7. Rim / Front Left  
Out of Bodywork / Scratch -



8. Fender / Front Left  
Bodywork / Dent -




9. Door / Front Left  
Paint / Scratch / Line -



10. Door / Back Left  
Paint / Scratch / Line -



11. Rim / Back Left  
Out of Bodywork / Scratch -



12. Fender / Back Left  
Bodywork / Dent -



13. Bumper / Back  
Bodywork / Dent -




14. Tailgate  
Bodywork / Dent -




15. Fender / Back Right  
Bodywork / Dent -



16. Rim / Back Right  
Out of Bodywork / Scratch -




17. Rocker Panel / Center Right  
Bodywork / Dent -



18. Door / Front Right  
Bodywork / Dent -





19. Mirror Shell / Front Right  
Paint / Scratch / Line -



20. Fender / Front Right  
Bodywork / Dent -



21. Rim / Front Right  
Out of Bodywork / Scratch -



22. Roof  
Bodywork / Dent / Hail Area -



## Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	✓		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	⚠

## Test Drive Inspection

Other Checks			
Brakes	✓	Steering	✓
Suspension	⚠		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓		
Equipments Test			
Steering   Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	✓
Engine Noise	⚠		

✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage

⚠ Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

☐ Not tested