


Vehicle details

VIN	VF3CCHMRP KT074446	Brand	PEUGEOT	Maintenance date	-
Licence Plate	ZT-13-3T	Model	208 Blue Lease Active 1.2 PureTech 82 5d	Maintenance mileage	-
Registration date	09/08/2019	Year	2019	Exterior Color	Black Metallic
Odometer	98 682 km	Engine size	1199	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	22/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

Removable element

Rear parcel shelf	✓
-------------------	---

Technical Document

Spare key	✗
User manual	✓
Warranty booklet	✓
Remote key	✓

Tyres

Continental 185/65/15 All seasons 7.0 mm			Continental 185/65/15 All seasons 6.0 mm	
Continental 185/65/15 All seasons 7.0 mm			Continental 185/65/15 All seasons 7.5 mm	

Exterior


3



●●

Part	Door
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

4



●●●●

Part	Wing
Position	Back right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

5



●●●●

Part	Door
Position	Back right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

6



●●●●

Part	Door
Position	Front right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

7



●●●●●

Part	Wing
Position	Front right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

8



●●●●●

Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

9



●●●●●●●●●●

Part	Roof
Position	-
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

Interior damage

1



Part	Spare key
Position	-
Damages	Missing
Severity	-
Repair mode	Replace

2



Part	Fabric seat
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning