



PEUGEOT 2008

2008 1.6 e-HDi 115ch FAP BVM6 Féline Titane

VIN NO VF3CU9HD8EY028656
Registration Number DD107SC



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

Customer	BCAauto Encheres	Report Number	P20250507091557
Inspection Date / Place	2025-05-07 / BCA ANGOULEME	Cosmetic Grade	3

Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Exempt Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Grey	Engine Size (cc)	1560
Engine Size	1.6	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Charging Cables		NEDC CO2 Rating (q/km)	105

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			






Equipment

Central locking	Radio	Alloys wheels	Cruise control
Power assisted steering	Electrically folding wing mirrors	Rear parking sensors	Tow ball
Front fog lamps	Satellite navigation		

Equipment Details

Seat Heating	Front	Air Conditioning	Yes
Sunroof Type	Fixed Panoramic		

Cosmetic Damage



Component	Damage	Comments
1 Floor Carpet	Interior / Dirty	
2 Floor Carpet	Interior / Holed	
3 Panel Filling / Front Left	Interior / Dirty	
4 Panel Filling / Front Right	Interior / Dirty	
5 Rim / Front Left	Out of Bodywork / Scratch	
6 Fender / Front Left	Bodywork / Dent / Deformation	
7 Door / Back Left	Paint / Scratch / Scuff	
8 Shield / Back	Bodywork / Dent / Deformation	
9 Rim / Front Right	Out of Bodywork / Scratch	



1. Floor Carpet
Interior / Dirty -



2. Floor Carpet
Interior / Holed -



3. Panel Filling / Front Left
Interior / Dirty -



4. Panel Filling / Front Right
Interior / Dirty -



5. Rim / Front Left
Out of Bodywork / Scratch -



6. Fender / Front Left
Bodywork / Dent / Deformation -



7. Door / Back Left
Paint / Scratch / Scuff -



8. Shield / Back
Bodywork / Dent / Deformation -



9. Rim / Front Right
Out of Bodywork / Scratch -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut ✔

✔ No troubles detected, good condition or correct tests, according to vehicle age and mileage

❗ Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

☐ Not tested

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.