



PEUGEOT 2008 Diesel

2008 1.6 bluehdi Active 100cv my16

VIN NO VF3CUBHY6HY005843
Registration Number FH034VA



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-01-27	-	-	136134 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2017-02-28	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20251009094316
Inspection Date / Place	2025-10-09 / BCA Lodi	Cosmetic Grade	5


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Black	Engine Size (cc)	1560
Engine Size	1.6	No of Doors	5
Body Type	SUV	Drive Train	Front
Seat Colour	Black	No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	97

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment

Central locking	Alloys wheels	Volante multifuncion	Remote adjusting wing mirrors
Cruise control	Tyre Mobility Kit	Power assisted steering	Digital Radio
Parcel Shef	Remote central locking	Trip Computer	Stability control

Wheels & Tyres



Mounted Tires

Tyre / Wheel Type	Four Seasons	
	KLEBER	195/60//R16 - 89H / 3 mm
	KLEBER	195/60//R16 - 89H / 3 mm
	FIRESTONE	195/60//R16 - 89H / 2 mm
	FIRESTONE	195/60//R16 - 89H / 2 mm

Cosmetic Damage

22 Danni

0 Danni



Component		Damage	Comments
1	Pillar / Front Left	Bodywork / Dent / Hail Area	
2	Hood	Bodywork / Dent / Hail Area	
3	Roof	Bodywork / Dent / Hail Area	
4	Bumper / Front	Paint / Scratch / Line	
5	Bumper / Back	Bodywork / Dent	
6	Tailgate	Bodywork / Dent	
7	Fender / Front Left	Paint / Chipping	
8	Door / Back Right	Bodywork / Dent	
9	Pillar / Front Right	Bodywork / Dent / Hail Area	
10	Door / Front Left	Paint / Scratch / Line	
11	Fender / Back Left	Bodywork / Dent	
12	Door / Front Right	Bodywork / Dent	


13	Mirror Shell / Front Right	Paint / Scratch / Line
14	Fender / Back Right	Bodywork / Dent / Hail Area
15	Door / Back Left	Paint / Scratch / Line
16	Rim / Front Left	Out of Bodywork / Scratch
17	Rim / Front Right	Out of Bodywork / Scratch
18	Rim / Back Left	Out of Bodywork / Scratch
19	Mirror Repeater / Left	Glass Break
20	Rim / Back Right	Out of Bodywork / Scratch
21	Fender / Front Right	Bodywork / Dent
22	Windshield / Front	Glass Break



1. Pillar / Front Left
Bodywork / Dent / Hail Area -



2. Hood
Bodywork / Dent / Hail Area -



3. Roof
Bodywork / Dent / Hail Area -




4. Bumper / Front
Paint / Scratch / Line -



5. Bumper / Back
Bodywork / Dent -



6. Tailgate
Bodywork / Dent -



7. Fender / Front Left
Paint / Chipping -



8. Door / Back Right
Bodywork / Dent -



9. Pillar / Front Right
Bodywork / Dent / Hail Area -



10. Door / Front Left
Paint / Scratch / Line -



11. Fender / Back Left
Bodywork / Dent -



12. Door / Front Right
Bodywork / Dent -



13. Mirror Shell / Front Right
Paint / Scratch / Line -




14. Fender / Back Right
Bodywork / Dent / Hail Area -



15. Door / Back Left
Paint / Scratch / Line -



16. Rim / Front Left
Out of Bodywork / Scratch -



17. Rim / Front Right
Out of Bodywork / Scratch -



18. Rim / Back Left
Out of Bodywork / Scratch -




19. Mirror Repeater / Left
Glass Break -



20. Rim / Back Right
Out of Bodywork / Scratch -



21. Fender / Front Right
Bodywork / Dent -



22. Windshield / Front
Glass Break -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	!		
Clutch			
Clutch Functioning	✓		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	✓

Test Drive Inspection

Other Checks			
Brakes	✓	Steering	✓
Suspension	✓		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓		
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	!
Engine Noise	!		
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			