



Peugeot 308 (UKL): 1YAM194

Vinnumber:	VF3LCYHYPLS157233	Versionname:	308 SW Style 1.5BlueHDi S&S 100pk/cv 5p
First Registrationdate:	30/06/2020	Fiscalpower:	
Expertise Mileage:	98584	Power Kw:	75
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Maintenancebook present		
Type of GPS storage	HD		

Tyres

	205/55/16/91 H			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				205/55 R 16 91 H
Tyre size FR				205/55 R 16 91 H
Tyre size RL				205/55 R 16 91 H
Tyre size RR				205/55 R 16 91 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Interior, Stain, Cleaning





Bonnet, Stone chip(s), Acceptable



Alloy rim FL, Scratch(es), Acceptable



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Acceptable



Door RL, Dent(s) and scratch(es), Acceptable





Step L, Dent(s) and scratch(es), Spot repair



Internal boot lining L, Scratch(es), Acceptable



Internal boot lining R, Scratch(es), Acceptable



Bumper R, Scratch(es), Repair and paint (complete)



Alloy rim RR, Scratch(es), Repair and paint (complete)



Tyre RR, Tear, Replace



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)



Tyre FR, Tear, Replace



Alloy rim FR, Scratch(es), Repair and paint (complete)



Outer sill R, Scratch(es), Acceptable

