



Peugeot 308 (UKL): 1YNU063

Vinnnumber:	VF3LCYHYPLS239509	Versionname:	308 SW Active 1.5BlueHDI S&S 100pk/cv 5p
First Registrationdate:	14/10/2020	Fiscalpower:	
Expertise Mileage:	131095	Power Kw:	75
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	dans 6200 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	205/55/16/91 H			
Summer tyres:	Fr.L.	Vredestein: 7 mm	Fr.R.	Vredestein: 7 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm
Tyre profile depth FL				7.0
Tyre profile depth FR				7.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/55 R 16 91 H
Tyre size FR				205/55 R 16 91 H
Tyre size RL				205/55 R 16 91 H
Tyre size RR				205/55 R 16 91 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Floor covering FL, Worn, Acceptable



Windscreen, Repaired, Acceptable



Bonnet, Stone chip(s), Acceptable



Bumper F, Scratch(es), Acceptable



Bumper grille, Scratch(es), Acceptable



Alloy rim RL, Scratch(es), Repair and paint (complete)



Door FL, Dent(s), Acceptable



Door FL, Scratch(es), Touch up



Outer sill L, Dent(s), Acceptable



Bumper R, Dent(s) and scratch(es), Acceptable



Boot carpet, Damaged, Forfeit



Alloy rim FR, Scratch(es), Repair and paint (complete)



Door RR, Dent(s), Acceptable

