



Peugeot 308 (UKL): 1YNT859

Vinnumber:	VF3LCYHYPLS239524	Versionname:	308 SW Active 1.5BlueHDI S&S 100pk/cv 5p
First Registrationdate:	14/10/2020	Fiscalpower:	
Expertise Mileage:	119518	Power Kw:	75
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	in 16500 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Maintenancebook present		
Type of GPS storage	HD		

Tyres

	205/55/16/91 V			
Summer tyres:	Fr.L.	Pirelli: 6 mm	Fr.R.	Pirelli: 6 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 5 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				6.0
Tyre profile depth RR				5.0
Tyre size FL				205/55 R 16 91 V
Tyre size FR				205/55 R 16 91 V
Tyre size RL				205/55 R 16 91 V
Tyre size RR				205/55 R 16 91 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				264
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Floor covering FL, Dirty, Cleaning



Engine insulation, Damaged, Replace



Windscreen, Stone chip(s), Windscreen repair



Central pillar L, Dent(s) and scratch(es), Spot repair



Door FL, Dent(s) and scratch(es), Spot repair



Wing FL, Scratch(es), Acceptable



Outer door handle FL, Scratch(es), Acceptable



Door FL, Scratch(es), Touch up



Boot lid covering R, Scratch(es), Acceptable



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)





Alloy rim FR, Scratch(es), Acceptable



Door RR, Dent(s) and scratch(es), Acceptable



Door FR, Dent(s), Paintless dent repair

