



Peugeot 308 (UKL): 1YNT901

Vinnumber:	VF3LCYHYPLS239528	Versionname:	308 SW Active 1.5BlueHDI S&S 100pk/cv 5p
First Registrationdate:	14/10/2020	Fiscalpower:	
Expertise Mileage:	94834	Power Kw:	75
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	NOT OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	205/55/16/94 V			
Summer tyres:	Fr.L.	Firestone: 6 mm	Fr.R.	Firestone: 6 mm
	Re.L.	Firestone: 6 mm	Re.R.	Firestone: 6 mm
Tyre profile depth FL	6.0			
Tyre profile depth FR	6.0			
Tyre profile depth RL	6.0			
Tyre profile depth RR	6.0			
Tyre size FL	205/55 R 16 94 V			
Tyre size FR	205/55 R 16 94 V			
Tyre size RL	205/55 R 16 94 V			
Tyre size RR	205/55 R 16 94 V			
Tyre type FL	Summer			
Tyre type FR	Summer			
Tyre type RL	Summer			
Tyre type RR	Summer			
Tyre make FL	258			
Tyre make FR	258			
Tyre make RL	258			
Tyre make RR	258			

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Service, Maintenance, Check



Door panel RR, Scratch(es), Acceptable



Bumper F, Scratch(es), Acceptable



Bonnet, Stone chip(s), Acceptable



Bumper moulding F, Scratch(es), Acceptable



Headlight L, Scratch(es), Acceptable



Door FL, Dent(s), Spot repair



Wing RL, Dent(s) and scratch(es), Acceptable



Alloy rim RL, Scratch(es), Acceptable



Alloy rim FL, Scratch(es), Acceptable



Step L, Scratch(es), Acceptable



Wing FL, Scratch(es), Acceptable



Door FL, Dent(s) and scratch(es), Acceptable



Door RL, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Rear light L, Broken, Replace



Wing RR, Dent(s) and scratch(es), Acceptable



Outer sill R, Dent(s), Repair and paint (complete)



Alloy rim FR, Scratch(es), Acceptable



Outside rear-view mirror housing R, Chemical polution, Acceptable



Alloy rim RR, Scratch(es), Acceptable



Door FR, Dent(s) and scratch(es), Acceptable



Step R, Scratch(es), Acceptable



Roof, Dent(s), Acceptable

