

Peugeot 308 (UKL): 1YPH798

Vinnumber:	VF3LCYHYPLS245480	Versionname:	308 SW Active 1.5BlueHDI S&S 100pk/cv 5p
First Registrationdate:	26/10/2020	Fiscalpower:	
Expertise Mileage:	98856	Power Kw:	75
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Battery functioning	Yes		
Registration Certificate Car (BE)	Yes		
Maintenance	OK		

Options

Type of Maintenance book	Digital maintenance	Luggage cover	
Type of GPS storage	HD	Type of Tow bar	No Tow bar
GPS			
Number of keys total	1		

Tyres

Tyre size RL	205/55 R 16 91 V
Tyre type FL	Summer
Tyre type RL	Summer
Tyre profile depth FR	6.0
Tyre profile depth RR	6.0
Tyre size FR	205/55 R 16 91 V
Tyre make FR	2480

205/55/16/91 V

Summer tyres:	Fr.L.	Vredestein: 6 mm	Fr.R.	Vredestein: 6 mm
	Re.L.	Vredestein: 6 mm	Re.R.	Vredestein: 6 mm

Tyre size RR	205/55 R 16 91 V
Tyre make RR	2480
Tyre profile depth FL	6.0
Tyre size FL	205/55 R 16 91 V
Tyre make FL	2480
Tyre profile depth RL	6.0
Tyre type FR	Summer
Tyre type RR	Summer
Tyre make RL	2480

Assistance equipment

Number of charging cables (normal)	0	Compressor	Yes
Number of charging cables (rapid charge)	0		
Repair kit	Yes		

Ignition key, Missing, Replace



Floor covering FL, Missing, Check



Floor covering R, Missing, Check



Floor covering FR, Missing, Check



Steering wheel, Worn, Acceptable



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)



Bonnet, Scratch(es), Acceptable



Wing FL, Scratch(es), Acceptable



Door RL, Dent(s), Acceptable



Alloy rim RL, Scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Acceptable



Mirror side repeater L, Scratch(es), Acceptable



Door window FL, Scratch(es), Replace




Bumper R, Scratch(es), Repair and paint (complete)



Boot carpet, Stain, Cleaning




Rear window, Scratch(es), Check




Tailgate / Boot, Dent(s), Acceptable



Step R, Dent(s), Acceptable



Wing FR, Scratch(es), Repair and paint (complete)



Door FR, Dent(s), Acceptable



Alloy rim FR, Scratch(es), Acceptable



Roof pillar R, Scratch(es), Acceptable



Door window FR, Scratch(es), Replace



Alloy rim RR, Scratch(es), Acceptable

