



PEUGEOT 308 SW: 1YQL629

Vinnumber:	VF3LCYHZJLS268562	Versionname:	308 SW 1.5 BlueHDi 130 DPF S/S Allure
First Registrationdate:	5/11/2020	Fiscalpower:	96kW/130pk 5D/P Man-6
Expertise Mileage:	184833	Power Kw:	
Bodytype:		Body colour	Light Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	c415
Fueltype:	Diesel		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Radio
Number keys remote	1	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		Fog lights (front)
Cruise Control		
Steering wheel multifunctional		
Navigation with screen		
Airco electronic		
Rims alloy		

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Degree of wear

205/55/16/91 H				
Winter tyres:	Fr.L.	BF Goodrich: 3 mm	Fr.R.	BF Goodrich: 3 mm
	Re.L.	BF Goodrich: 4 mm	Re.R.	BF Goodrich: 4 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/55 R 16 91 H
Tyre size FR				205/55 R 16 91 H
Tyre size RL				205/55 R 16 91 H
Tyre size RR				205/55 R 16 91 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2485
Tyre make FR				2485
Tyre make RL				2485
Tyre make RR				2485

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Backrest cover RL, Scratch(es), Smart repair



Bumper F, Scratch(es), Repair and paint (complete)



Alloy rim RL, Scratch(es), Acceptable



Wing RL, Dent(s), Acceptable




Door FL, Dent(s), Paintless dent repair



Internal boot lining R, Scratch(es), Smart repair



Internal boot lining L, Scratch(es), Smart repair



Boot lid covering R, Scratch(es), Smart repair



Bumper R, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Acceptable



Outside rear-view mirror housing R, Scratch(es), Acceptable



Door RR, Dent(s), Acceptable

