



Peugeot 308 (UKL): 1YWA265

Vinnnumber:	VF3LCYHZJLS311591	Versionname:	308 SW Business 1.5BlueHDi S&S 130pk/cv 5p
First Registrationdate:	7/01/2021	Fiscalpower:	
Expertise Mileage:	98522	Power Kw:	96
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Battery functioning	Yes		
Registration Certificate Car (BE)	Yes		
Maintenance	OK		
Maintenance	in 20800 km		

Options

Type of Maintenance book	Maintenancebook present	Luggage cover	
Type of GPS storage	HD	Type of Tow bar	No Tow bar
GPS			
Number of keys total	2		

Tyres

Tyre size RL	205/55 R 16 91 H
Tyre type FL	Winter
Tyre type RL	Winter
Tyre profile depth FR	3.0
Tyre profile depth RR	4.0
Tyre size FR	205/55 R 16 91 H
Tyre make FR	2484

205/55/16/91 H			
Winter tyres:	Fr.L.	Fulda: 3 mm	Fr.R.
	Re.L.	Fulda: 5 mm	Re.R.
			Fulda: 4 mm

Tyre size RR	205/55 R 16 91 H
Tyre make RR	2484
Tyre profile depth FL	3.0
Tyre size FL	205/55 R 16 91 H
Tyre make FL	2484
Tyre profile depth RL	5.0
Tyre type FR	Winter
Tyre type RR	Winter
Tyre make RL	2484

Assistance equipment

Number of charging cables (normal)	0	Compressor	Yes
Number of charging cables (rapid charge)	0		
Repair kit	Yes		

Seat cover FR, Stain, Cleaning



Roof liner, Stain, Cleaning



Seat cover R, Stain, Cleaning



Alloy rim RL, Scratch(es), Acceptable



Door FL, Dent(s) and scratch(es), Acceptable



Outer door handle FL, Scratch(es), Acceptable



Alloy rim FL, Scratch(es), Acceptable



Wing RL, Dent(s), Acceptable



Door RL, Scratch(es), Acceptable



Boot carpet, Stain, Cleaning



Boot lid covering R, Scratch(es), Smart repair



Bumper R, Scratch(es), Acceptable



Parking sensor R, Repaired, Check



Tailgate / Boot, Scratch(es), Acceptable



Door FR, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Repair and paint (complete)



Tyre FR, Tear, Replace



Alloy rim RR, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s) and scratch(es), Acceptable

