



Peugeot 308 (UKL): 2AHN984

Vinnumber:	VF3LCYHZJLS324976	Versionname:	308 SW Business 1.5BlueHDi S&S 130pk/cv 5p
First Registrationdate:	7/04/2021	Fiscalpower:	
Expertise Mileage:	155214	Power Kw:	96
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	18700 km ou 7 mois		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	1	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

205/55/16/91 V				
Summer tyres:	Fr.L.	Fulda: 7 mm	Fr.R.	Fulda: 7 mm
	Re.L.	Fulda: 8 mm	Re.R.	Fulda: 8 mm
Tyre profile depth FL				7.0
Tyre profile depth FR				7.0
Tyre profile depth RL				8.0
Tyre profile depth RR				8.0
Tyre size FL				205/55 R 16 91 V
Tyre size FR				205/55 R 16 91 V
Tyre size RL				205/55 R 16 91 V
Tyre size RR				205/55 R 16 91 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2484
Tyre make FR				2484
Tyre make RL				2484
Tyre make RR				2484

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Floor covering FL, Worn, Check



Seat cover FR, Stain, Cleaning



Interior, Dirty, Forfeit



Seat cover RL, Stain, Cleaning



Seat cover FL, Burned, Replace




Floor covering FL, Burned, Smart repair



Interior covering A pillar L, Burned, Smart repair



Roof liner, Burned, Smart repair



Ignition key, Missing, Replace



Interior, Waterinfiltration, Chemical cleaning



Roof liner, Dirty, Cleaning



Bonnet, Scratch(es), Acceptable



Windscreen, Scratch(es), Acceptable



Bonnet, Stone chip(s), Acceptable



Door FL, Scratch(es), Acceptable



Wing FL, Scratch(es), Acceptable



Alloy rim FL, Scratch(es), Acceptable



Mirror side repeater L, Broken, Replace



Outside rear-view mirror base L, Scratch(es), Acceptable



A-pillar left, Scratch(es), Acceptable



Wing RL, Scratch(es), Repair and paint (complete)



Brand badge R, Deformed / Strained, Replace



Tailgate / Boot, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Acceptable



Internal boot lining L, Scratch(es), Acceptable



Rear window, Scratch(es), Acceptable



Internal boot lining R, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Smart repair



Boot carpet, Damaged, Forfeit



Rear light L, Waterinfiltration, Replace



Rear light L tailgate, Waterinfiltration, Replace



Door RR, Scratch(es), Acceptable



Door FR, Dent(s) and scratch(es), Acceptable



Door RR, Dent(s), Paintless dent repair



Alloy rim RR, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Broken, Replace and paint



Mirror side repeater R, Broken, Replace



Roof pillar R, Scratch(es), Acceptable



Roof, Chemical polution, Repair and paint (complete)

