



Peugeot 308 (UKL): 2AKQ313

Vinnumber:	VF3LCYHZKLS279455	Versionname:	308 SW GT 1.5BlueHDi S&S 130pk/cv 5p EAT8
First Registrationdate:	27/04/2021	Fiscalpower:	
Expertise Mileage:	121803	Power Kw:	96
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Battery functioning	No		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	1	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Maintenancebook missing		
Type of GPS storage	HD		

Tyres

	225/45/17/94 Y			
Summer tyres:	Fr.L.	Hankook: 5 mm	Fr.R.	Hankook: 5 mm
	Re.L.	Uniroyal: 8 mm	Re.R.	Uniroyal: 8 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				8.0
Tyre profile depth RR				8.0
Tyre size FL				225/45 ZR 17 94 Y
Tyre size FR				225/45 ZR 17 94 Y
Tyre size RL				225/45 ZR 17 91 Y
Tyre size RR				225/45 ZR 17 91 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				260
Tyre make FR				260
Tyre make RL				265
Tyre make RR				265

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Ignition key, Missing, Replace



Data erasure, Maintenance, Check

No pictures to display

Seat cover R, Stain, Cleaning




Seat cover FR, Stain, Cleaning



Door panel FL, Broken, Forfeit



Alloy rim FL polished, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable



Alloy rim RL polished, Scratch(es), Acceptable



Step L, Dent(s) and scratch(es), Acceptable




Bumper R, Scratch(es), Acceptable



Wing RR, Dent(s) and scratch(es), Acceptable



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

