

Inspection Protocol



PEUGEOT 308 SW 1.5 BLUEHDI

Vehicle information

License plate	HZC57X	Inspected by	T.H.
Year model	2019	Date of inspection	2025-03-13
Manuf. year/month	2019-10	City	Björkvik
First day in traffic	2019-10	Keys	2
Colour	Vit	Service book	Ja
Mileage	88 070 km	Latest service	2024-07-22
Fuel	Diesel	Mileage at the latest service	78 720 km
Transmission	Manuell	Summer tires	16" alu-fälg 5/5/5/5
Engine effect	96 kW	Winter tires	plåtfälg dubbat 6/6/6/6

Damages

Location	Damage	Comments	Costs excluding VAT
Bumper, Rear	Repor, 3-10 cm		100 €
Door, Front right	Scratches 30-100 mm		100 €

Total excl. VAT	200 €
-----------------	-------

Images

[See all images in large format](#)













SERVICEJOURNAL

Datum: 2022.12.19 km: 47323

Normala körförhållanden ☐ Krävande körförhållanden ☐

Verkstadsstämpel

Nästa service vid _____ (km) eller senast datum 2023.12.19

Datum: ____/____/____ km: ____

Normala körförhållanden ☐ Krävande körförhållanden ☐

Verkstadsstämpel

Nästa service vid _____ (km) eller senast datum ____/____/____

* Beroende på vilket av de två villkoren som uppfylls först.

SERVICEJOURNAL

Datum: 2024.07.22 km: 78763

Normala körförhållanden ☐ Krävande körförhållanden ☐

Verkstadsstämpel

Nästa service vid _____ (km) eller senast datum 2025.07.22

Datum: ____/____/____ km: ____

Normala körförhållanden ☐ Krävande körförhållanden ☐

Verkstadsstämpel

Nästa service vid _____ (km) eller senast datum ____/____/____

* Beroende på vilket av de två villkoren som uppfylls först.





Stötfångare Bak Repor, 3-10 cm 1 100 kr





Dörr Höger fram Repor 3-10 cm 1 100 kr