

Inspection Protocol



PEUGEOT 308 SW 1.5 BLUEHDI

Vehicle information

License plate	CJB02A	Inspected by	C.C.
Year model	2020	Date of inspection	2025-04-10
Manuf. year/month	2020-01	City	Björkvik
First day in traffic	2020-01	Keys	2
Colour	Vit	Service book	Ja
Mileage	91 900 km	Latest service	2024-07-22
Fuel	Diesel	Mileage at the latest service	70 600 km
Transmission	Manuell	Summer tires	16" alu-fälg 4/4/5/5
Engine effect	96 kW	Winter tires	plåtfälg dubbat 6/6/6/6

Damages

Location	Damage	Comments	Costs excluding VAT
Sills, Left	Dents below 30 mm		70 €
Bumper, Front	Scratches below 30 mm		70 €
Bonnet	Paint damages		-
Total excl. VAT			140 €

Images

[See all images in large format](#)


















Trösklar Vänster Bucklor under 3 cm 800 kr



Stötfångare Fram Repor under 3 cm 800 kr



Motorhuv Lackskador



