

Inspection Protocol

PEUGEOT 308 SW 1.5 BLUEHDI

Vehicle information

License plate	DAS56B	Inspected by	C.C.
Year model	2020	Date of inspection	2025-04-10
Manuf. year/month	2020-01	City	Björkvik
First day in traffic	2020-01	Keys	2
Colour	Vit	Service book	Ja
Mileage	87 060 km	Latest service	2024-12-03
Fuel	Diesell	Mileage at the latest service	84 910 km
Transmission	Manuell	Summer tires	16" alu-fälg 4/4/4/4
Engine effect	96 kW	Winter tires	plåtfälg dubbat 7/7/7/7

Damages

Location	Damage	Comments	Costs excluding VAT
Glass, Windshield	Chip		30 €

Total excl. VAT 30 €

Images

[See all images in large format](#)














SERVICEJOURNAL

Datum: 2023 12 27 km: 58977
 Normala körförhållanden Krävande körförhållanden

PEUGEOT
 Verkstadsstämpel
Belins Bil AB
 Aukt. verkstad 6651
 Järnogatan 2
 Avesta

Nästa service vid _____ (km) eller senast datum 2023 12 27

Datum: 2024 01 15 km: 62752
 Normala körförhållanden Krävande körförhållanden

PEUGEOT
 Verkstadsstämpel
Belins Bil AB
 Aukt. verkstad 6651
 Järnogatan 2
 Avesta

Nästa service vid _____ (km) eller senast datum 2025 01 15

Datum: 2024 12 03 km: 29711
 Normala körförhållanden Krävande körförhållanden

PEUGEOT
 Verkstadsstämpel
Bilkompaniet Dalarna
 Aukt. öterfors. 6077022
 Avesta
 Org. nr 556040-3650

Nästa service vid _____ (km) eller senast datum . / . *

Datum: _____ km: _____
 Normala körförhållanden Krävande körförhållanden

PEUGEOT
 Verkstadsstämpel

Nästa service vid _____ (km) eller senast datum . / . *

* Beroende på vilket av de två villkoren som uppfylls först.









Glas Vindruta Stenskott 300 kr





