



Peugeot 308: H588KK

Vinnumber:	VF3LRHNPJKS431637	Versionname:	308 1.2 PureTech 81kW Active SW
First Registrationdate:	5/03/2020	Fiscalpower:	
Expertise Mileage:	158714	Power Kw:	81
Bodytype:		Body colour	White
Gearbox:	MAN 6 VIT	Paint type	Opaque
Transmission:	Front	Type of rims (mounted)	Aluminium
Fueltype:	Petrol	Parking lot	609
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Telephone equipment
Number keys remote	1	Central consol F
GPS		Luggage cover
GPS storage		Rear parking sensors
GPS storage	HD	Hook
Autom climate control		Roof rack
Windows electric F		
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 55 / 16 / 94 / H / Aluminium	2,0 mm	Continental	All season
	Right	205 / 55 / 16 / 94 / H / Aluminium	3,0 mm	Continental	All season
Rear	Left	205 / 55 / 16 / 94 / V / Aluminium	3,0 mm	Bridgestone	Summer
	Right	205 / 55 / 16 / 94 / V / Aluminium	3,0 mm	Bridgestone	Summer

Assistance equipment

Emergency spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Full-screen GPS, Scratch(es), Replace



Interior, Dirty, Cleaning





Door panel RR, Scratch(es), Replace



Sill trim RR, Scratch(es), Replace



Sill trim RL, Scratch(es), Replace



Door FL, Scratch(es), Repair and paint (complete)



Wing RL, Dent(s), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)



Wing FL, Scratch(es), Polish



Tyre RL, Tear, Replace



Outside rear-view mirror housing L, Broken, Replace and paint



Mirror side repeater L, Broken, Replace



Roof pillar L, Scratch(es), Polish



Bumper F, Scratch(es), Repair and paint (partial)



Door RR, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Replace and paint



Bumper R, Scratch(es), Repair and paint (complete)



Luggage compartment cover, Broken, Replace



Boot carpet, Broken, Replace



Boot lid covering R, Scratch(es), Replace

