



Peugeot 308: H639DL

Vinnumber:	VF3LRHNPJKS467942	Versionname:	308 1.2 PureTech 81kW Blue Lease SW
First Registrationdate:	11/02/2020	Fiscalpower:	
Expertise Mileage:	155571	Power Kw:	81
Bodytype:		Body colour:	Dark Blue metaallak
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Type of rims (mounted):	Steel
Fueltype:	Petrol	Parking lot:	166
Number of seats:	5		
Type of rims (mounted):	Steel		
Maintenance needed:	Yes		

Options

Number of keys total	2	Telephone equipment
Number keys remote	2	Central consol F
GPS		Luggage cover
GPS storage		Rear parking sensors
Manual climate control		Hook
Windows electric F		
Radio multimedia		

Degree of wear

	205/55/16/91 H			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 5,8 mm
	Re.L.	Michelin: 5,8 mm	Re.R.	Michelin: 6 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				5.8
Tyre profile depth RL				5.8
Tyre profile depth RR				6.0
Tyre size FL				205/55 R 16 91 H
Tyre size FR				205/55 R 16 91 H
Tyre size RL				205/55 R 16 91 H
Tyre size RR				205/55 R 16 91 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Service, Maintenance, Execute



Door RL, Scratch(es), Repair and paint (complete)



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing FL, Scratch(es), Repair and paint (complete)



Bonnet, Stone chip(s), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Polish



Door RR, Dent(s), Paintless dent repair



Boot lid covering R, Scratch(es), Replace



Bumper R, Scratch(es), Repair and paint (complete)

