



PEUGEOT 308 SW: 1XNX496			
Vinnumber:	VF3LRHNPJKS503883	Versionname:	1.2 PureTech 110 S&S Style
First Registrationdate:	24/02/2020	Fiscalpower:	
Expertise Mileage:	108010	Power Kw:	81
Bodytype:		Body colour	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2524
Fueltype:	Petrol		
Maintenance	OK		
Maintenance	dans 14600 km		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options			
Number of keys total	2	Luggage cover	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar removable
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Type of GPS storage	HD		

Limited Technical Inspection

Degree of wear

205/55/16/91 T				
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/55 R 16 91
Tyre size FR				205/55 R 16 91
Tyre size RL				205/55 R 16 91
Tyre size RR				205/55 R 16 91
Tyre type FL				Winte
Tyre type FR				Winte
Tyre type RL				Winte
Tyre type RR				Winte
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		
Total cost ex VAT			1056,56
Bumper F, Scratch(es), Repair and paint (complete)			289,07



Bumper moulding F, Scratch(es), Replace

162,64



Alloy rim FL, Scratch(es), Acceptable

0,00



Outside rear-view mirror housing L, Scratch(es), Acceptable

0,00



Wing RL, Dent(s), Paintless dent repair

93,06



Bumper R, Scratch(es), Repair and paint (complete)

289,07



Tailgate / Boot, Scratch(es), Acceptable

0,00



Wheel aperture RR, Scratch(es), Acceptable

0,00



Wing RR, Dent(s), Paintless dent repair

93,06



Alloy rim FR, Scratch(es), Repair and paint (complete)

129,66

