



PEUGEOT 3008^{HY}: GC-681-GW

Vinnumber:	VF3M4DGZUMS213505	Versionname:	
First Registrationdate:	8/10/2021	Fiscalpower:	
Expertise Mileage:	115834	Power Kw:	
Bodytype:	SUV	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Plug-in hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Luggage cover
Number keys remote	2	Rear view camera
GPS big screen color		

Tyres

225/55/18/102 V				
Summer tyres:	Fr.L.	Pirelli: 60%	Fr.R.	Pirelli: 60%
	Re.L.	Pirelli: 35%	Re.R.	Pirelli: 55%
Tyre profile depth FL				4.3
Tyre profile depth FR				4.4
Tyre profile depth RL				5.8
Tyre profile depth RR				4.7
Tyre size FL				225/55 R 18 102 V
Tyre size FR				225/55 R 18 102 V
Tyre size RL				225/55 R 18 102 V
Tyre size RR				225/55 R 18 102 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				264
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	1		

Inner door sill RR, Dent(s) and scratch(es), Repair and paint (complete)



Seat cover FL, Tear, Smart repair LEATHER



Tyres, No damage, Acceptable




Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre RR, Tear, Replace



Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)





Tyre RL, Tear, Replace



Alloy rim FL bitone/polychrome, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Door RL, Scratch(es), Polish



Bumper F, Scratch(es), Acceptable



Wing RR, Dent(s), Repair and paint (complete)



Door RR, Dent(s), Acceptable



Boot lid covering R, Scratch(es), Smart repair



Bumper corner RR, Unclassped, Dismount/Mount

