



Peugeot 3008: N246VZ

Vinnnumber:	VF3M4DGZUMS255808	Versionname:	3008 1.6 PHEV 165kW Allure Pack Business E-EAT8
First Registrationdate:	29/04/2022	Fiscalpower:	
Expertise Mileage:	116506	Power Kw:	133
Bodytype:		Body colour:	Metallic Bleu Vertigo
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Type of rims (mounted):	Aluminium
Fueltype:	Hybrid Petrol	Parking lot:	602
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
Number keys remote	2	Central consol F
GPS		Luggage cover
Autom climate control		Headlights Xenon/LED/Laser
Windows electric F		Front parking sensors
Radio multimedia		Rear parking sensors

Degree of wear

225/55/18/102 V				
Summer tyres:	Fr.L.	Michelin: 3,7 mm	Fr.R.	Michelin: 3,2 mm
	Re.L.	Michelin: 2,2 mm	Re.R.	Michelin: 1,6 mm
Tyre profile depth FL				3.7
Tyre profile depth FR				3.2
Tyre profile depth RL				2.2
Tyre profile depth RR				1.6
Tyre size FL				225/55 R 18 102 V
Tyre size FR				225/55 R 18 102 V
Tyre size RL				225/55 R 18 102 V
Tyre size RR				225/55 R 18 102 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	1

User's manual, Missing, Replace

No pictures to display

Door FL, Scratch(es), Repair and paint (complete)



Door RL, Chemical polution, Polish



Wing RL, Scratch(es), Repair and paint (complete)



Bonnet, Stone chip(s), Repair and paint (complete)



Wing RR, Scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Charging cable (normal), Missing, Replace



Roof, Chemical polution, Polish

