



Peugeot 5008 (KKL): 1WEG374

Vinnnumber:	VF3MCYHJZKL044289	Versionname:	5008 GT-Line 1.5 BlueHDi S/S 130pk/cv 5p
First Registrationdate:	10/05/2019	Fiscalpower:	
Expertise Mileage:	93439	Power Kw:	96
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	319900.0		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Maintenancebook present		
Type of GPS storage	HD		

Tyres

205/55/19/97 V				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				205/55 R 19 97 V
Tyre size FR				205/55 R 19 97 V
Tyre size RL				205/55 R 19 97 V
Tyre size RR				205/55 R 19 97 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Bonnet, Stone chip(s), Acceptable



Central pillar L, Dent(s) and scratch(es), Acceptable



Step L, Dent(s) and scratch(es), Acceptable



Door RL, Dent(s), Repair and paint (complete)



Wing RL, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Step R, Dent(s) and scratch(es), Acceptable



Door RR, Dent(s), Repair and paint (complete)



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Acceptable





Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Roof, Chemical polution, Polish

