



## PEUGEOT 5008: 1WTT904

Vinnumber:	<b>VF3MCYHZJKS357446</b>	Versionname:	<b>1.5 BlueHdi 96kW S&amp;S Active</b>
First Registrationdate:	<b>12/09/2019</b>	Fiscalpower:	
Expertise Mileage:	<b>162420</b>	Power Kw:	<b>96</b>
Bodytype:		Parking lot	<b>3413</b>
Gearbox:	<b>MAN 6 VIT</b>	Type of rims (mounted)	<b>Aluminium</b>
Transmission:		Body colour	<b>Black</b>
Fueltype:	<b>Diesel</b>		
Certificate of Conformity	<b>Yes</b>		
Type of rims (mounted)	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Registration Certificate Home (BE)	<b>No</b>		
Registration Certificate Car (BE)	<b>Yes</b>		
Maintenance	<b>OK</b>		

## Options

Radio multimedia		Luggage cover	
Steering wheel multifunctional		Rear parking sensors	
Type of GPS storage	<b>HD</b>	Front parking sensors	
Type of GPS	<b>GPS big screen color</b>	Type of Tow bar	<b>Tow bar fixed</b>
Cruise Control			
Type of climate control	<b>Autom climate control</b>		
Number of keys total	<b>2</b>		
Type of headlighting	<b>Headlighting Halogen</b>		
Type of Lining	<b>Lining fabrics</b>		

## Limited Technical Inspection

## Tyres

Tyre size RL	<b>215/65 R 17 99 V</b>
Tyre type FL	<b>Summer</b>
Tyre type RL	<b>Summer</b>
Tyre profile depth FR	<b>6.0</b>
Tyre profile depth RR	<b>7.0</b>
Tyre make FR	<b>265</b>
Tyre size FR	<b>215/65 R 17 99 V</b>
Tyre make RR	<b>265</b>
Tyre size RR	<b>215/65 R 17 99 V</b>

## 215/65/17/99 V

Summer tyres:	Fr.L.	<b>Uniroyal: 6 mm</b>	Fr.R.	<b>Uniroyal: 6 mm</b>
	Re.L.	<b>Uniroyal: 7 mm</b>	Re.R.	<b>Uniroyal: 7 mm</b>

Tyre profile depth FL	<b>6.0</b>
Tyre make FL	<b>265</b>
Tyre size FL	<b>215/65 R 17 99 V</b>
Tyre type FR	<b>Summer</b>
Tyre profile depth RL	<b>7.0</b>
Tyre type RR	<b>Summer</b>
Tyre make RL	<b>265</b>

## Assistance equipment

Number of charging cables (normal)	<b>0</b>	Compressor	<b>Yes</b>
Number of charging cables (rapid charge)	<b>0</b>	Jack	<b>Yes</b>

Total cost ex VAT	<b>700,90</b>
Bonnet, Scratch(es), Acceptable	<b>0,00</b>



Door RL, Dent(s), Spot repair 144,58



Wing trim RL, Scratch(es), Acceptable 0,00



Luggage compartment cover, Worn, Acceptable 0,00



Tailgate / Boot, Bad repair, Repair and paint (complete) 411,74



Bumper R, Scratch(es), Acceptable 0,00



Door RR, Dent(s), Spot repair 144,58



Wing RR, Dent(s), Acceptable 0,00

