

INSPECTION REPORT



End Of Contract

GENERAL INFO

File	285541
License plate	1XJW904
Vehicle identification number	VF3MCYHZJKS484749
Dossier	2019276192
Make	Peugeot 3008 1.5BHDi 96kW Allu
Mileage	112091.00
First registration	20/01/2020
	16/06/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
84	Door Front Left // Repair & Painting	Y
91	Rocker Panel Left // Smart Repair Medium	Y
106	Door Rear Left // Polish	Y
116	Wing Rear Left // Polish	Y
133	Bumper Rear // Painting	N
159	Rear Bonnet / Rear Window / Replace	Y
165	Roof // Polish	Y
174	Light / Rear Right / Replace	Y
183	Wing Rear Right // Painting	N
196	Door Rear Right // Polish	Y
330	Wheel Two Tone Rear Right // Repair	N
860	Interior Cleaning // Small	Y


Damage Pictures




Door Rear Right // Polish-scratch






Wheel Two Tone Rear Right // Repair-scratch




Wing Rear Right // Painting-scratch



Light / Rear Right / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch





Bumper Rear // Painting-scratch



Wing Rear Left // Polish-scratch






Rocker Panel Left // Smart Repair Medium-scratch



Roof // Polish-scratch



Door Rear Left // Polish-scratch



Door Front Left // Repair & Painting-scratch + dent





Interior Cleaning // Small-stain