



Peugeot 3008 (UKL): 1YQC072

Vinnnumber:	VF3MCYHZJLS233373	Versionname:	3008 Active 1.5 BlueHDi S&S 130pk/cv 5p
First Registrationdate:	2/11/2020	Fiscalpower:	
Expertise Mileage:	146280	Power Kw:	96
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	+26700 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Maintenancebook present		
Type of GPS storage	HD		

Tyres

215/65/17/103 V				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				215/65 R 17 103 V
Tyre size FR				215/65 R 17 103 V
Tyre size RL				215/65 R 17 103 V
Tyre size RR				215/65 R 17 103 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Interior covering A pillar L, Stain, Acceptable



Interior, Damaged, Check



Seat cover R, Stain, Cleaning



Armrest, Scratch(es), Acceptable



Seat cover FR, Stain, Cleaning



Centre console, Scratch(es), Acceptable



Bumper F, Scratch(es), Acceptable



Alloy rim FL, Scratch(es), Repair and paint (complete)



Wing trim FL, Scratch(es), Replace



Door FL, Scratch(es), Acceptable



Step L, Scratch(es), Acceptable



Door RL, Scratch(es), Acceptable



Wing trim RL, Scratch(es), Acceptable



Alloy rim RL, Scratch(es), Acceptable



Internal boot lining R, Scratch(es), Replace



Internal boot lining L, Scratch(es), Replace



Boot lid covering R, Scratch(es), Replace



Bumper R, Scratch(es), Acceptable





Bumper trim R, Scratch(es), Acceptable



Alloy rim RR, Scratch(es), Repair and paint (complete)



Door RR, Dent(s), Paintless dent repair



Outside rear-view mirror housing R, Scratch(es), Acceptable



Mirror side repeater R, Scratch(es), Replace



Alloy rim FR, Scratch(es), Acceptable



Step R, Scratch(es), Acceptable

