



PEUGEOT 5008: 1YMS116

Vinnumber:	VF3MCYHZJLS234437	Versionname:	1.5 BlueHDi 96kW S&S Allure
First Registrationdate:	21/10/2020	Fiscalpower:	
Expertise Mileage:	100009	Power Kw:	96
Bodytype:		Body colour:	Black
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2126
Fueltype:	Diesel		
Maintenance:	OK		
Maintenance:	+ 6400 km		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Radio multimedia:		Type of Tow bar:	No Tow bar
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining semi-artificial leather		
Type of climate control:	Autom climate control		
Type of GPS storage:	HD		

Limited Technical Inspection

Degree of wear

225/55/18/102 Y				
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				4.6
Tyre profile depth FR				4.6
Tyre profile depth RL				5.6
Tyre profile depth RR				5.6
Tyre size FL				225/55 R 18 102 Y
Tyre size FR				225/55 R 18 102 Y
Tyre size RL				225/55 R 18 102 Y
Tyre size RR				225/55 R 18 102 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				265
Tyre make RR				265

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT:	1765,16
Seat cover FL, Worn, Acceptable:	0,00



Engine insulation, Hole, Replace

189,76



Bonnet, Scratch(es), Acceptable

0,00



Bumper F, Scratch(es), Acceptable

0,00



Bumper spoiler F, Scratch(es), Repair and paint (complete)

0,00



Alloy rim RL polished, Rust, Repair and paint (complete)

199,04



Door RL, Scratch(es), Acceptable

0,00



Alloy rim FL polished, Rust, Repair and paint (complete)

199,04



Boot lid covering R, Scratch(es), Acceptable

0,00



Tailgate / Boot, Scratch(es), Acceptable

0,00



Bumper trim R, Scratch(es), Acceptable

0,00



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

199,04



Door FR, Scratch(es), Acceptable

0,00



Wing RR, Dent(s), Paintless dent repair

93,06



Alloy rim RR polished, Rust, Repair and paint (complete)

199,04



Roof, Dent(s) and scratch(es), Repair and paint (complete)

686,18

