


PEUGEOT 5008: 1YPM152

Vinnumber:	VF3MCYHZJLS251282	Versionname:	1.5 BlueHdi 96kW S&S Allure
First Registrationdate:	27/10/2020	Fiscalpower:	
Expertise Mileage:	97798	Power Kw:	96
Bodytype:		Parking lot:	2601
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Body colour:	Green
Fueltype:	Diesel		
Certificate of Conformity:	Yes		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		
Registration Certificate Home (BE):	No		
Registration Certificate Car (BE):	Yes		

Options

Radio multimedia		Luggage cover	
Steering wheel multifunctional		Rear parking sensors	
Type of GPS:	GPS big screen color	Sun Roof electric	
Cruise Control		Front parking sensors	
Type of climate control:	Autom climate control	Panoramic roof	
Number of keys total:	2	Type of Tow bar:	Tow bar fixed
Type of headlighting:	Headlighting Halogen		
Type of Lining:	Lining semi-leather		

Limited Technical Inspection
Tyres

Tyre size RL	205/55 R 19 97 H
Tyre type FL	Winter
Tyre type RL	Winter
Tyre profile depth FR	3.0
Tyre profile depth RR	3.0
Tyre make FR	261
Tyre size FR	205/55 R 19 97 H
Tyre make RR	256
Tyre size RR	205/55 R 19 97 H

205/55/19/97 H

Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 3 mm
Tyre profile depth FL				4.0
Tyre make FL				261
Tyre size FL				205/55 R 19 97 H
Tyre type FR				Winter
Tyre profile depth RL				4.0
Tyre type RR				Winter
Tyre make RL				256

Assistance equipment

Number of charging cables (normal)	0	Jack	Yes
Emergency spare wheel	Yes		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 1398,74

Interior, Worn, Acceptable 0,00



Alloy rim FL polished, Scratch(es), Repair and paint (complete) 199,04



Alloy rim RL polished, Scratch(es), Repair and paint (complete) 199,04



Boot moulding, Scratch(es), Polish 0,00



Rear light R tailgate, Scratch(es), Polish 0,00



Rear light L tailgate, Scratch(es), Polish 0,00



Rear window, Scratch(es), Replace 0,00



Alloy rim RR polished, Scratch(es), Repair and paint (complete) 199,04



Wing trim RR, Scratch(es), Replace 181,93



Wing RR, Dent(s) and scratch(es), Repair and paint (complete) 420,65



Alloy rim FR polished, Scratch(es), Repair and paint (complete) 199,04



Door FR, Scratch(es), Acceptable 0,00



Door RR, Dent(s), Acceptable 0,00



Roof, Chemical polution, Polish 0,00

