



Peugeot 5008 (KKL): 2AWP499

Vinnumber:	VF3MCYHZMMS184784	Versionname:	5008 Allure Pack 1.5 BlueHdi S/S 130pk/cv 5p
First Registrationdate:	18/08/2021	Fiscalpower:	
Expertise Mileage:	91189	Power Kw:	96
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar removable
Type of Maintenance book	Maintenancebook present		
Type of GPS storage	HD		

Tyres

	225/55/18/102 Y			
Summer tyres:	Fr.L.	Bridgestone: 2 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Michelin: 2 mm	Re.R.	Michelin: 2 mm
Tyre profile depth FL				2.0
Tyre profile depth FR				2.0
Tyre profile depth RL				2.0
Tyre profile depth RR				2.0
Tyre size FL				225/55 R 18 102 Y
Tyre size FR				225/55 R 18 102 Y
Tyre size RL				225/55 R 18 102 Y
Tyre size RR				225/55 R 18 102 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

MOT certificate, Non-conforme, Replace



Seat cover FL, Worn, Check



Backrest cover FL, Worn, Check



Seat cover FR, Worn, Check




Alloy rim FL polished, Chemical polution, Acceptable



Door FL, Scratch(es), Acceptable




Alloy rim RL polished, Scratch(es), Acceptable



Roof pillar L, Dent(s), Acceptable



Bumper trim R, Scratch(es), Acceptable



Alloy rim RR polished, Chemical polution, Acceptable



Door FR, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s) and scratch(es), Acceptable



Wing trim RR, Scratch(es), Acceptable

