



Peugeot 5008 (KKL): 1YKD771

Vinnumber:	VF3MCYHZRLS113056	Versionname:	5008 Allure 1.5 BlueHdi S/S 130pk/cv 5p EAT8
First Registrationdate:	18/09/2020	Fiscalpower:	
Expertise Mileage:	89885	Power Kw:	96
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	in 24200 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	1	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Maintenancebook present		
Type of GPS storage	HD		

Tyres

225/55/18/102 V				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 6 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				6.0
Tyre size FL				225/55 R 18 102 V
Tyre size FR				225/55 R 18 102 V
Tyre size RL				225/55 R 18 102 V
Tyre size RR				225/55 R 18 102 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Ignition key, Missing, Replace



Interior, Not original part, Repair/replace (lump sum)



Seat cover FR, Stain, Cleaning




Backrest cover RM, Stain, Cleaning



Seat cover FL, Stain, Acceptable



Seat cover RL, Stain, Acceptable



Bonnet, Dent(s), Repair and paint (complete)



Bumper moulding F, Scratch(es), Acceptable



Bumper moulding F, Scratch(es), Acceptable



Alloy rim FL polished, Scratch(es), Repair and paint (complete)





Mirror side repeater L, Scratch(es), Replace



Door FL, Scratch(es), Acceptable



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing trim RL, Scratch(es), Acceptable



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Boot carpet, Dirty, Cleaning



Internal boot lining L, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Bumper R, Scratch(es), Spot repair



Bumper R, Scratch(es), Acceptable



Rear wiper arm, Incomplete, Replace



Tailgate / Boot, Scratch(es), Repair/replace (lump sum)




Wheel aperture RR, Dent(s) and scratch(es), Acceptable



Wheel aperture RL, Dent(s) and scratch(es), Spot repair



Rear spoiler, Dent(s), Repair and paint (complete)



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Acceptable



Door FR, Dent(s) and scratch(es), Acceptable



Mirror side repeater R, Scratch(es), Replace



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Spot repair



Bodywork, Not original part, Check



Roof, Dent(s), Acceptable

