



Peugeot 5008 (KKL): 1YXN341

Vinnnumber:	VF3MCYHZULS294262	Versionname:	5008 GT 1.5 BlueHdi S/S 130pk/cv 5p EAT8
First Registrationdate:	22/01/2021	Fiscalpower:	
Expertise Mileage:	133232	Power Kw:	96
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	+28300 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar removable
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

205/55/19/97 W				
Summer tyres:	Fr.L.	Semperit: 6 mm	Fr.R.	Semperit: 6 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				205/55 R 19 97 W
Tyre size FR				205/55 R 19 97 W
Tyre size RL				205/55 R 19 97 V
Tyre size RR				205/55 R 19 97 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2477
Tyre make FR				2477
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Seat cover FL, Worn, Acceptable



Windscreen, Crack, Replace



Alloy rim FL, Scratch(es), Acceptable



Door RL, Dent(s), Paintless dent repair



Step L, Dent(s), Paintless dent repair



Tailgate / Boot, Repaired, Check



Alloy rim RR, Scratch(es), Repair and paint (complete)



Step R, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Replace



Outside rear-view mirror housing R, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Acceptable

