



Peugeot 3008 (UKL): 1YXR093

Vinnumber:	VF3MCYHZULS313680	Versionname:	3008 GT 1.5 BlueHDi S&S 130pk/cv 5p EAT8
First Registrationdate:	25/01/2021	Fiscalpower:	
Expertise Mileage:	161231	Power Kw:	96
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar removable
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	225/55/18/102 Y			
Summer tyres:	Fr.L.	Hankook: 6 mm	Fr.R.	Hankook: 6 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				225/55 R 18 102 Y
Tyre size FR				225/55 R 18 102 Y
Tyre size RL				225/55 R 18 102 V
Tyre size RR				225/55 R 18 102 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				260
Tyre make FR				260
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Seat cover FL, Tear, Replace



Backrest cover FL, Tear, Replace



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)



Bumper moulding F, Broken, Replace



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Boot carpet, Damaged, Acceptable



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Alloy rim FR polished, Scratch(es), Repair and paint (complete)





Outside rear-view mirror housing R, Scratch(es), Acceptable



Door trim RR, Scratch(es), Acceptable

