



Peugeot 5008 (KKL): 2BBM161

Vinnumber:	VF3MCYHZUMS192861	Versionname:	5008 Allure 1.5 BlueHDi S/S 130pk/cv 5p EAT8
First Registrationdate:	21/09/2021	Fiscalpower:	
Expertise Mileage:	194530	Power Kw:	96
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	NOT OK		
Maintenance	dépassé de 11600 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar removable
Type of Maintenance book	Maintenancebook present		
Type of GPS storage	HD		

Tyres

	225/55/18/102 Y			
Summer tyres:	Fr.L.	Continental: 2 mm	Fr.R.	Continental: 2 mm
	Re.L.	Michelin: 1 mm	Re.R.	Michelin: 1 mm
Tyre profile depth FL				2.0
Tyre profile depth FR				2.0
Tyre profile depth RL				1.0
Tyre profile depth RR				1.0
Tyre size FL				225/55 R 18 102 Y
Tyre size FR				225/55 R 18 102 Y
Tyre size RL				225/55 R 18 102 V
Tyre size RR				225/55 R 18 102 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	No	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Service, Maintenance, Check



Floor covering FL, Worn, Acceptable



Backrest cover FL, Worn, Acceptable



Engine insulation, Damaged, Replace



Central pillar L, Scratch(es), Acceptable



Tyre RL, Worn, Check



Door RL, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable



Tyre repair kit, Missing, Replace



Bumper R, Scratch(es), Spot repair



Bumper R, Scratch(es), Spot repair



Rear light L tailgate, Scratch(es), Acceptable



Central pillar R, Dent(s) and scratch(es), Spot repair



Door RR, Dent(s), Spot repair



Tyre RR, Worn, Check



Alloy rim RR polished, Scratch(es), Acceptable



Door RR, Scratch(es), Acceptable



Roof pillar R, Dent(s), Paintless dent repair



Roof, Dent(s), Acceptable

