


Vehicle details

VIN	VF3MCYHZU MS216234	Brand	PEUGEOT	Maintenance date	-
Licence Plate	LL104IH	Model	5008 1.5 Bluehdi 130 S&s Eat8 Allure Pack 96K	Maintenance mileage	-
Registration date	30/11/2021	Year	1000	Exterior Color	Grey Metallic
Odometer	63 734 km	Engine size	1499	interior Color	Black
Fuel	Diesel	Body Type	SUV CrossOver	Next technical inspection	01/11/2024
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details


Inspection date	19/11/2024	Inspection loc.	Hödlmayr Logistics GmbH
-----------------	------------	-----------------	-------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
GPS system	✓
7 seater	✓
Xenon projectors	✓
Anti-fog lights	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Heating seats	✓

Removable element



Technical Document

User manual	✓
Log books	✓
Spare key	✓
Remote key	✓

Tyres

Michelin 225/55/18 V Summer 4.4 mm		Michelin 225/55/18 V Summer 4.3 mm	
Michelin 225/55/18 V Summer 4.7 mm		Michelin 225/55/18 V Summer 4.6 mm	

Exterior

1		Part	Windscreen	2		Part	Bonnet
		Position	-			Position	-
		Damages	Stone impact			Damages	Improper repair
		Severity	-			Severity	-
		Repair mode	For info			Repair mode	Repair

3



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	For info

4



Part	Door
Position	Front left
Damages	Scratched
Severity	-
Repair mode	For info

5



Part	Door
Position	Back left
Damages	Scratched
Severity	-
Repair mode	For info

6



Part	Door sill
Position	Back left
Damages	Dent & Chips
Severity	-
Repair mode	Repair

7



Part	Door
Position	Front right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

Interior damage

8



Part	Interior cleaning
Position	-
Damages	Not carried out
Severity	-
Repair mode	Lumpsum

Others

9



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Paintworks