

Vehicle details

VIN	VF3MRHNSM LS233955	Brand	PEUGEOT	Maintenance date	-
Licence Plate	J8-55-TG	Model	3008 Blue Lease Premium PureTech 130 5d	Maintenance mileage	-
Registration date	29/10/2020	Year	2020	Exterior Color	Black Metallic
Odometer	129 720 km	Engine size	1199	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	09/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

Removable element

Rear parcel shelf	✓
-------------------	---

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres

Pirelli 205/55/19 Summer 4.0 mm		Pirelli 205/55/19 Summer 4.5 mm	
Michelin 205/55/19 Summer 6.5 mm		Michelin 205/55/19 Summer 6.5 mm	

Exterior

4



●●

Part	Alloy wheel 19"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

5



●●●

Part	Door
Position	Front left
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

6



●●●●

Part	Door
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Repair

7



●●

Part	Step plate
Position	Back left
Damages	Dent & Chips
Severity	-
Repair mode	For info

8



●●

Part	Alloy wheel 19"
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

9



●●

Part	Wing
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Repair

10



●●●●

Part	Door
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Repair

11



●●

Part	Door
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

12



●●

Part	Alloy wheel 19"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

13



●●

Part	Roof
Position	-
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

Interior damage

1



●

●

Part	Fabric seat
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

2




●

●

Part	Seat
Position	Front left
Damages	Worn out
Severity	-
Repair mode	For info

3



●

Part	Fabric seat
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning