


## Vehicle details

|                   |                    |              |                                        |                           |               |
|-------------------|--------------------|--------------|----------------------------------------|---------------------------|---------------|
| VIN               | VF3MRHNSM MS232205 | Brand        | PEUGEOT                                | Maintenance date          | -             |
| Licence Plate     | P7-66-GJ           | Model        | 5008 Blue Lease Active PureTech 130 5d | Maintenance mileage       | -             |
| Registration date | 31/03/2022         | Year         | 2022                                   | Exterior Color            | Blue Metallic |
| Odometer          | 165 286 km         | Engine size  | 1199                                   | interior Color            | Grey          |
| Fuel              | Petrol             | Body Type    | -                                      | Next technical inspection | -             |
| Seats             | -                  | Transmission | Manual                                 | CO2                       | -             |
| Doors             | 5                  | Gears        | 6                                      |                           |               |

## Inspection Details

|                 |            |                 |              |
|-----------------|------------|-----------------|--------------|
| Inspection date | 18/08/2025 | Inspection loc. | Dekra Ayvens |
|-----------------|------------|-----------------|--------------|



## Generic equipment

|                            |   |
|----------------------------|---|
| Automated air-conditioning | ✓ |
| Cruise control             | ✓ |
| GPS system                 | ✓ |
| 7 seater                   | ✓ |
| Alloy wheel rims           | ✓ |
| Heating seats              | ✓ |
| Electric seats             | ✓ |
| Tow                        | ✓ |
| Metallic paint             | ✓ |
| Central locking            | ✓ |
| Electric windows           | ✓ |
| Park Distance Control      | ✓ |
| Audio System               | ✓ |
| Led lighting               | ✓ |

## Removable element

|            |   |
|------------|---|
| Load cover | ✓ |
|------------|---|

## Technical Document

|                  |   |
|------------------|---|
| User manual      | ✓ |
| Warranty booklet | ✓ |
| Spare key        | ✓ |
| Remote key       | ✓ |

## Tyres

|                                     |                                     |
|-------------------------------------|-------------------------------------|
| Continental 215/65/17 Summer 4.5 mm | Continental 215/65/17 Summer 4.5 mm |
| Continental 215/65/17 Summer 6.5 mm | Continental 215/65/17 Summer 6.0 mm |

## Exterior

3



|             |                 |
|-------------|-----------------|
| Part        | Alloy wheel 17" |
| Position    | Front left      |
| Damages     | Scratched       |
| Severity    | -               |
| Repair mode | Lumpsum repair  |

●

●

4



|             |                  |
|-------------|------------------|
| Part        | Door             |
| Position    | Back left        |
| Damages     | Scratched        |
| Severity    | Length (cm) > 10 |
| Repair mode | Repair           |

●

●

5




|             |              |
|-------------|--------------|
| Part        | Step plate   |
| Position    | Back left    |
| Damages     | Dent & Chips |
| Severity    | -            |
| Repair mode | For info     |

●

●

6



|             |               |
|-------------|---------------|
| Part        | Roof moulding |
| Position    | Right         |
| Damages     | Dented        |
| Severity    | -             |
| Repair mode | Replace       |

●

●

7



|             |             |
|-------------|-------------|
| Part        | Step plate  |
| Position    | Front right |
| Damages     | Dented      |
| Severity    | -           |
| Repair mode | For info    |

●

●

8



|             |                  |
|-------------|------------------|
| Part        | Bumper           |
| Position    | Front            |
| Damages     | Scratched        |
| Severity    | Length (cm) > 10 |
| Repair mode | Repair           |

●

●

9



|             |              |
|-------------|--------------|
| Part        | Windscreen   |
| Position    | -            |
| Damages     | Stone impact |
| Severity    | -            |
| Repair mode | For info     |

●

●

10



|             |                    |
|-------------|--------------------|
| Part        | Roof               |
| Position    | -                  |
| Damages     | Dented             |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Smart Repair       |

●

●

### Interior damage

1



Part

Position

Damages

Severity

Repair mode

Seat back

Front left

Misaligned


-

Adjust

●

●

2



Part

Position

Damages

Severity

Repair mode

Interior roof lining

-

Stained/dirty

-

Cleaning

●

●

●

●