


Vehicle details

VIN	VF3MRHNSU KL141989	Brand	PEUGEOT	Maintenance date	-
Licence Plate	J0-41-GB	Model	5008 Blue Lease Premium Avantage PT 130 EAT 5d	Maintenance mileage	-
Registration date	31/07/2020	Year	2020	Exterior Color	Black Metallic
Odometer	155 556 km	Engine size	1199	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	02/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓

Removable element

Spare wheel kit	✓
Load cover	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Michelin 205/65/19 Summer 6.0 mm	Michelin 205/65/19 Summer 5.5 mm
Goodyear 205/65/19 Summer 8.5 mm	Goodyear 205/65/19 Summer 8.5 mm

Exterior

1



●●

Part	Bonnet
Position	-
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

2



●●

Part	Bumper moulding
Position	Front left
Damages	Broken
Severity	-
Repair mode	Replace

3



●●

Part	Spoiler
Position	Front left
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

4



●●

Part	Bumper
Position	Front right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

5



●●

Part	Alloy wheel 19"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

6



●●●

Part	Door
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

7



●●

Part	Door
Position	Back right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

8



●●

Part	Door
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

9



●●●●

Part	Door
Position	Front left
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

10



●●

Part	Wing
Position	Front left
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

11



●●

Part	Wing
Position	Back left
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

Interior damage

12



Part	Leather seat
Position	Front left
Damages	Worn out
Severity	-
Repair mode	For info