



PEUGEOT 5008: GG-678-RG

Vinnumber:	VF3MRHNSUNS096746	Versionname:	
First Registrationdate:	31/05/2022	Fiscalpower:	
Expertise Mileage:	161481	Power Kw:	
Bodytype:	SUV	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Petrol	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Luggage cover
Number keys remote	1	Rear view camera
GPS big screen color		
GPS storage		
GPS storage	HD	

Tyres

215/65/17/103 V				
Summer tyres:	Fr.L.	Goodyear: 45%	Fr.R.	Goodyear: 40%
	Re.L.	Goodyear: 15%	Re.R.	Goodyear: 60%
Tyre profile depth FL				5.3
Tyre profile depth FR				5.6
Tyre profile depth RL				7.1
Tyre profile depth RR				4.4
Tyre size FL				215/65 R 17 103 V
Tyre size FR				215/65 R 17 103 V
Tyre size RL				215/65 R 17 103 V
Tyre size RR				215/65 R 17 103 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	No	Compressor	No
Remote ignition key (no insert), Missing, Repair/replace (lump sum)			



Interior, Stain, Cleaning



Roof liner, Tear, Repair/replace (lump sum)



Interior, Stain, Cleaning



Inner door sill RL, Dent(s) and scratch(es), Repair and paint (complete)



Tyres, No damage, Acceptable



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Polish



Bumper moulding F, Scratch(es), Acceptable



Door RR, Dent(s), Acceptable



Door FR, Dent(s), Repair and paint (complete)



Wing FR, Dent(s) and scratch(es), Acceptable



Compressor, Missing, Repair/replace (lump sum)



Tyre repair kit, Missing, Repair/replace (lump sum)



Boot carpet, Tear, Replace



Rubber seal for boot lid, Tear, Replace



Bumper corner RL, Scratch(es), Dismount/Mount



Luggage compartment cover, Deformed / Strained, Replace



Internal boot lining R, Scratch(es), Smart repair



Internal boot lining L, Scratch(es), Smart repair



Bumper R, Scratch(es), Replace



Bodywork, Not original part, Acceptable

