

VF3PMCFAC88078151

PEUGEOT 107 107 70



TECHNICAL CONDITION

Engine	Brakes	Steering
Engine starts	Brake operation	Sounds normal
Engine operation		
Clutch	Gear Box	
Engine compartment dry (oil)	Clutch operation	Automatic shift
Fume quantity	Idle sounds normal	Manual shif
Sounds normal	Clutch biting point	Warning light OK

COMPLAINT NOTE

The technical check includes a visual check of the vehicles without removal of any components.
The condition of the mechanical components cannot be rated.

LEVELS

Coolant fluid
Brakes fluid

EQUIPMENT TEST

Electric windows test
Audio equipment
Navigation equipment
AC / Heating system
Central lock system test

TYRES

Profile depths

FL 6 mm FR 5 mm

BR 5 mm BL 7 mm

Additional tyre profile depths

A B

C D

CONTROL LIGHTS

Dashboard
ABS
Oil
Airbag
Engine
Brakes
Steering
DPF
Diesel heaters
Traction control / ESP / Stability control
4x4
Alternator / Battery



No defects recognizable, good condition or positive tests based on vehicle's age and mileage.



Registered damage that needs to be repaired by the buyer.



Not verifiable.