



Peugeot 108: H177SL

Vinnumber:	VF3PSCFB7KR049132	Versionname:	108 1.0 e-VTi 53kW Blue Lease Executive
First Registrationdate:	30/04/2020	Fiscalpower:	
Expertise Mileage:	103291	Power Kw:	53
Bodytype:		Paint type	Metalic
Gearbox:	MAN 5 VIT	Body colour	Black
Transmission:	Front	Parking lot	596
Fueltype:	Petrol	Type of rims (mounted)	Aluminium
Number of seats	4		
Maintenance needed	No		
Type of rims (mounted)	Aluminium		

Options

GPS	Telephone equipment
Number of keys total	2 Luggage cover
Windows electric F	
Radio multimedia	
Autom climate control	

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	165 / 60 / 15 / 81 / T / Aluminium	6,9 mm	Hankook	Winter
	Right	165 / 60 / 15 / 81 / T / Aluminium	5,7 mm	Hankook	Winter
Rear	Left	165 / 60 / 15 / 77 / T / Aluminium	8,1 mm	Vredestein	Winter
	Right	165 / 60 / 15 / 77 / T / Aluminium	7,8 mm	Vredestein	Winter

Assistance equipment

Number of charging cables (rapid charge)	0
Number of charging cables (normal)	0

Seat cover FL, Hole, Smart repair



Interior, Stain, Cleaning



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Door FL, Bad repair, Repair and paint (complete)



Bonnet, Stone chip(s), Repair and paint (complete)



Windscreen, Stone chip(s), Windscreen repair



Bumper F, Scratch(es), Repair and paint (complete)




Roof pillar R, Scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Roof, Scratch(es), Repair and paint (complete)

