

Vehicle details

VIN	VF3PSCFB7 LR057172	Brand	PEUGEOT	Maintenance date	-
Licence Plate	J7-26-NR	Model	108 Active 1.0 e-VTi 72pk 5d	Maintenance mileage	-
Registration date	23/09/2020	Year	2020	Exterior Color	Black Metallic
Odometer	44 266 km	Engine size	998	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	23/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Audio System	✓



Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Key	✓
Remote key	✓

Tyres

Continental 165/65/14 Summer 5.0 mm		Continental 165/65/14 Summer 7.0 mm	
Continental 165/65/14 Summer 6.5 mm		Continental 165/65/14 Summer 6.5 mm	

Exterior

1		Part	Sill	2		Part	Bonnet
		Position	Left			Position	-
		Damages	Dented			Damages	Chemical deposit
		Severity	Diameter (mm) > 20			Severity	-
		Repair mode	Repair			Repair mode	Lumpsum repair

3



●●●●●●●●

Part	Roof
Position	-
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

4



●●●●

Part	Roof post A/B/C
Position	Left
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

5



●●●

Part	Roof post A/B/C
Position	Right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair