


Vehicle details

VIN	VF3PSCFB7 LR058192	Brand	PEUGEOT	Maintenance date	-
Licence Plate	J1-21-JH	Model	108 Active 1.0 e-VTi 72pk 5d	Maintenance mileage	-
Registration date	19/08/2020	Year	2020	Exterior Color	White Solid
Odometer	48 904 km	Engine size	998	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	21/08/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Central locking	✓
Electric windows	✓
Audio System	✓

Removable element

Load cover	✓
------------	---

Technical Document

User manual	✓
Warranty booklet	✓
Key	✓
Remote key	✓

Tyres

Continental 165/65/14 Summer 4.0 mm	Continental 165/65/14 Summer 4.0 mm
Continental 165/65/14 Summer 6.0 mm	Continental 165/65/14 Summer 6.5 mm

Exterior

1		Part: Wing Position: Front left Damages: Dented Severity: Diameter (mm) > 20 Repair mode: Smart Repair	2		Part: Door Position: Back left Damages: Dented Severity: Diameter (mm) > 20 Repair mode: Smart Repair
3		Part: Wing Position: Back right Damages: Dent & Chips Severity: Diameter (mm) > 20 Repair mode: Repair	4		Part: Door Position: Back right Damages: Scratched Severity: - Repair mode: Repair

5



Part

Position

Damages

Severity

Repair mode

Wing

Front right

Dented

Diameter (mm) > 20

Repair

6



Part

Position

Damages

Severity

Repair mode

Roof

-

Dented

Diameter (mm) > 20

Smart Repair