

Vehicle details

VIN	VF3PSCFB7 LR069205	Brand	PEUGEOT	Maintenance date	-
Licence Plate	J3-97-XX	Model	108 Active 1.0 e-VTi 72pk 5d	Maintenance mileage	-
Registration date	12/11/2020	Year	2020	Exterior Color	Grey Metallic
Odometer	56 553 km	Engine size	998	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	14/08/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Audio System	✓

Removable element

Rear parcel shelf	✗
Spare wheel (wheel & tyre)	✓


Technical Document

Spare key	✓
Remote key	✓

Tyres

Bridgestone 165/65/14 T Summer 5.0 mm		Bridgestone 165/65/14 T Summer 5.0 mm	
Continental 165/65/14 T Summer 6.0 mm		Continental 165/65/14 T Summer 6.0 mm	

Exterior

3		Part	Bumper	4		Part	Door
		Position	Front			Position	Back left
5		Damages	Scratched	6		Damages	Dented
		Severity	Length (cm) > 10			Severity	Diameter (mm) > 20
		Repair mode	Repair			Repair mode	Repair
						Part	Wing
		Position	Back			Position	Back right
		Damages	Dent & Chips			Damages	Dented
		Severity	Diameter (mm) > 20			Severity	Diameter (mm) > 20
		Repair mode	Repair			Repair mode	Repair

7



●●●

Part	Door
Position	Back right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

8



●●

Part	Sill
Position	Right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

9



●●

Part	Door
Position	Front right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

Interior damage

1



Part

Rear parcel shelf

Position

-

Damages

Missing

Severity

-

Repair mode

Replace

2



Part

Interior cleaning

Position

-

Damages

Stained/dirty

Severity

-

Repair mode

Cleaning